



PROJECT SAMPLE REPORT

Date: Tuesday, 5 February 2019

Conditions: Warm and Dry, No Recent Sign of Rainfall

Prepared For: No One

Summary: 4 Issues Identified

Strata Defect Specialists Sydney
Suite 5, 101 George Street
Parramatta NSW 2150

P: 02 8007 3359
E: info@sdss.net.au
www.sdss.net.au

Strata Construction Consultants
PTY Ltd (CAN 614 027 851)



OFFICE. CEILING LINING SAGGING

Assigned To Builder



OFFICE. INCOMPLETE CEILING LINING

Assigned To Builder



OFFICE. WEST FACING WINDOW AREA. POOR FINISH TO COLUMN

Assigned To Builder



OFFICE SPACE. NORTH FACING OFFICE. POOR FINISH TO CEILING. SURFACE DAMAGE AND MARKS.

Assigned To Builder